From: Technical < Technical@amberseas.co.uk >

Subject: RE: References STERN TUBE STOP LEAK // AT

Date: 2 March 2017 at 10:09:32 GMT+2

To: Raimondas Strasinskas / BALTMARINE TRADING

<trading@baltmarine.eu>

Cc: Technical < Technical@amberseas.co.uk >

TOP URGENT

Dear Raimondas

Good morning

Please note that use ABCON didn't stop leakage luboil from sterntube in the full. We are reduced leakage in general on 90%, but when engine start and variable RPM in port, we have small leakages from sterntube. Areas of pollution approx. 15x15m, because we used gear oil inside sterntube.

Due a ballast condition leakage was every day 2,5 ltr, now 0,2 ltr Due a laden condition, leakage was every day 0,5 ltr, now 0 ltr. In the port or variable RMP - 0,1 -0,2 ltr

Now we have added 40ltrs of ABCON, 10 additional liters will be added soon. Total volume of oil is 560 Ltrs.

Best Regards Mr. Ilya Kudryavtsev Marine Superintendent